

22 June 2015

Samurai Farms Ltd 777 Samurai Road Razor Sharp Lane New Plymouth

Farm Supply Number: 88888

Dear Tom Cruise

Thank you for having us on your property to undertake a Dairy Efficient Wa ant of Fitness assessment of your dairy farm effluent infrastructure on 22 June 2015.

Please find included here full details of the assessment and the areas we thought worthwhile to bring to your attention.

Continuing good management of your system in an all to sold any future issues.

We recommend that you get your system r sess 'in 3 year's time.

Please do not hesitate to contact us if the half any questions.

Best Regards

Nicholas Tait

Nicholas Tait

Dairy Effluent 'WoF' Certified Assessor



Private Bag 3221 Hamilton 3240

Ph: 0278386792

Email: nicholas.tait@dairynz.co.nz



SUMMARY

Shed & all yards areas, & underpass drain to stone trap, WSP mechanical separator, then to clay-lined pond. Pond then pumps to small pod system.

Recommend that actual water use in the shed is measured.

Extend effluent lines to west of farm (ex. lease block).


No issues to date. Converted 5 years ago.

GOOD EFFLUENT INFRASTRUCTURE

There were a number of examples of good effluent infrastructure indentified vour property:

- · Checks ES soil moisture site.
- · Safety grating over top of pump sump
- Incoming flow protection under incoming pip g pond inle concre)
- All effluent areas appeared sealed & contained.
- Irrigation supply line size allows good flow capa. VC rubber-ring joint 110mm & 80mm) also looking to extend application area.
- Spreading sludges with tractor bucket ac ner in rmi ad activity requirements.
- · Pods are well maintained.

APPLICATION DEPT! TEST FOLL SISPRINKLERS OR CANNONS



Max depth (mm):	11.16
Average depth (mm):	3.02
Average Applicaton Rate (mm/hr):	3.07



RISK ASSESSMENT

Your effleunt systems has been assessed across a number of different areas. Acknowledging that your objective is to operate at a high level of good effluent management practice, there may be some areas identified on your property which we feel you need to address.

Please find details and information below regarding recommendations based on the observations we have made.

WOF

Regional Council Record Keeping - No Records

Risk Area	Why of Concern	Sugr, ested Action
Effluent record keeping	Good practice to record effluent application	Pecord pada k number, pump time and "ho arted pump - Records or e t application ar not 'ing kept. Recommend k application off effluent application
Solids application		chis increases the risk of eq. ment failure, over application or application to saturated soils going unnoticed, and therefore increases the risk of a non-compliance. A rain monitor is available that will turn the pump off if it rains.
Solids application		Effluent being applied within 7 metres of property boundary. Consent requires a minimum of 20m separation.

WOF

Stone Trap Area Sand Traps

A. ifluent contained

Risk Area	Whooncern	Suggested Action
Stone trap not well		Stone trap before stormwater
designed		diversion. Stone trap needs to be
		fully emptied and cleaned out
		before diversion is turned on.



Sump Score - Contained

Risk Area	Why of Concern	Suggested Action
Grate missing		Grate missing off collection sump at end of west yard entry race – safety risk to animals and people. Replace or extend grating

*



Shed Infrastructure - Potential for occasional discharge

Risk Area	Why of Concern	Suggested Action
Lane runoff		North yard entry - runoff from yard wash overflows to lane & paddock. Don't hose wash, extend sump or increase height of nib.

*

WOF

Housed Wintering Solid Storage - N/A

Risk Area	Why of Concern	Suggested Artion
Overflow from sludge bunker	Breach of regional council rules, risk of prosecution	Small amount of solids from separator have fallen or overflowed over back of bunker, empty none regularly or more from separator or in all concrete pad draining to store

*



Silage Stacks - N/A

Risk Area	Why of Concern	Sug. sted Action
Storm water diversion		nderpass and runoff from the road and nearly paddock is flooding the underr ass area, recommend that this is addressed.

Effluent Storage Integrity -

No slur, ing rholes

Risk Area	Why of Cot. 31.	Suggested Action
Effluent Storage Safety	Hea Lisa ty	Install signage, egress ladders, safety rope, or buoys - Single hot wire fence around pond is not adequate for safety purposes. No escape ladders or flotation devices are evident.
Pond may not be sealed		Cows have been grazed on the pond embankments, there is evidence that they have been up to the water line. This may damage the pond embankment and it is also possible that the cows may fall in and drown.

*



Safety Features

No risk areas were noted in this area.

*



Nutrient Budget Paperwork - Nutrient budget available and meets industry good practice



Solids Storage - All effluent contained/captured on adequate sealed surface

No risk areas were noted in this area.

*



Storage Capacity - Adequate (witin 25% of DESC)

No risk areas were noted in this area.

*



Storage Liner Assessment - Clay liner, no obvious leakage with supporting evidence that meets required standard.

No risk areas were noted in this area.

*



Underpass - Irrigated discharge to land

No risk areas were noted in this area.

*



Bridges and Culverts - N/A

No risk areas were noted in this area.

*



Feedpads - N/A

No risk areas were noted in this area.



Housed Wintering Facility - N A

No risk areas we's noted in this . a.

*



Standoff Loafing Pad (* istructed Facility) - N/A

No isk areas were ... his area.

*



Laneways - No obvious discharge to water

No risk areas were noted in this area.

*



Lines/Hydrants/Couplings - No obvious discharge to water

No risk areas were noted in this area.

*



Farm Drains - No sign of raw effluent in drain

No risk areas were noted in this area.

*



Solids land application system (bedding, separated solids) - Evenly spread inappropriate depths



Liquid irrigation application depth and soil risk - Meets required application depth i.e. consent/permitted activity

No risk areas were noted in this area.



Liquid Effluent Irrigation-Conveyance (pipes and hydrants) - No obvious leaks

No risk areas were noted in this area.

Liquid effluent irrigation - application to land - No sign of poor irrigation

No risk areas were noted in this area.



FARM INFORMATION

Samurai Farms Ltd

S/N: 88888

Fonterra Co-Operative Group Ltd

Herd size: 540	Milking Time (hrs): 4	Lactation start: 12/08/2013	End: 25/05/2014
Shed type: Rotary	Flood wash of yard: Water on backing gate	Total dairy shed wash vol/day (m³)	Measu. ed by: Flow Meter
Storm water diversion: Yes	All Year : No	Start diversion . 26/05/20	Stop 4iversion : 1/08/2015
Feed Pad : N/A	Months Used : 12	Avg daily w	/vg daily hrs on pad :
Stand-off pad used regularly? :	Stand-off pad how often used?	Und passes u. I frequently : Dai Use	

IRRIGATION

	Hrs pumped/day	Application dept. nm)	Volume (m³/hour)	Total daily ∨olume (m³)
Winter-Spring	4	3	25	100
Spring-Autumn	4	3	25	100

Irrigator type(s): Small Poris Pump (kw): 0

Technology in use: Pressure Gauge Gauge at pump: Yes

Alaman Gauge at irrigator: No

Alarms: 1/0 - Anti-siphon, 2/0 - her - Hi-low ressure switch on pump

SHED AND YARD

	(10	Sealed	Contained	Area (m²)	
Tanker Pad	S	Yes		205	If collected to effluent system
Shed roof	Ye				Roof dimensions (if not diverted)
Yard	'95	Ves	Yes	1048	
Yard Entry	s	Yes	No	291	2.2
Yard Exit	Yes	Yes	Yes		20 (2) 20 (3)
Any Other Yard Area	Yes	Yes	Yes	213	8 %

STONE TRAP

	Present	Sealed	Effluent Contained	Area (m²)
Stone Trap	Yes	Yes	Yes	32
Stone Trap Solids Bunker	No	N/A	N/A	

SAFETY FEATURES

Fence Type: 2 wire post Warning signs: No Rescue Buoy: No Egress ladders/ropes: No Level Indicator: No Anti-siphon: No

DAIRY EFFLUENT WARRANT OF FITNESS Page 7 of 8



FEEDPAD / HOUSED WINTERING FACILITY WASH VOLUMES AND USE

монтн	AVERAGE DAILY COWNUMBERS	AVERAGE DAILY HOURS ON PAD	AVERAGE DAILY WASH VOLUME (M³)
January	480	3.00	240
February	480	3.00	240
March	480	3.00	240
April	480	3.00	240
May	480	3.00	240
June	480	3.00	240
July	480	3.00	240
August	480	3 00	240
September	480	3.	240
October	480	70	240
November	480	3.0	240
December	480	J.00	240

OVERALL AVERAGE COW NUMBERS

OVERALL AVERAGE PAD HOURS

OVERALL AVERAGE WA 1 VC

7 OTAL MOVING 12 UN 12

DISCI AIMED

This Report represents our assessment of whether the effluent system on your farm meets the best industry practice as identified by the Dairy Effluent Warrant of Fitness (DE'WoF') Certification Advisory group as at the date of the assessor's inspection. The issue of the DE'WoF' Report (Report) is not a warranty or confirmation that the effluent system fully complies with any requirements of any relevant authority either as at the date of the issue of the Report or in the future. To the maximum extent permitted by law, any condition or warranty that would otherwise be implied into these terms and conditions is hereby excluded.

While all reasonable endeavours have been made to ensure the accuracy of the information contained in this Report, DairyNZ Limited, the administrators and assessors of the DE'WoF' programme do not accept responsibility for any loss or damage (whether direct, indirect, consequential or other), however caused (including through negligence), which you may directly or indirectly suffer in connection with your use of this Report, and expressly disclaims any and all liabilities contingent or otherwise that may arise from any such loss arising out of your use of or reliance on information contained on or accessed through this Report. You agree that the above exclusion of liability confer a benefit on the entities or persons listed above and are enforceable by each of them in accordance with the contracts (Privity) Act 1982.